


Please install the USB driver before connect the programmer to computer. This will avoid manually installed the driver.

For installing the USB driver on Win2000/XP:

Run the PL2303Xp2k.exe from the CD.

Once finished install the software driver, you can connect the programmer. The Windows will be able to detect the hardware and install the software automatically.

1. It may be found new hardware:



2. If your PC found the new hardware, then just like follow the windows installation process. This only happened when the first time install the programmer only. The final window should like this.




For installing the USB driver on Windows Vista 32 bit:


1. The Windows Vista will detect the new hardware and may not be able to find the driver itself.
2. Select “Other option” to locate the driver from the CD under directory: USB Driver for PL2303\Vista32
3. Then the Windows Vista should be able to install the driver successfully.
4. Under device manager of My Computer Property, user is able to find a new comport and check the comport number for the software use.

For install the Programmer Software:


3. Run the setup.exe from the CD.
4. The setup will run as:




5. Once the driver installed, we can continually install the software:



6. Till finished the installation



- 7. Go to the device manager of your PC to find out which serial port is assigned. Here is the port 3:**



8. Select the serial port. If you use the USB mode, the port number is 3 here. If you are using the serial mode, then the port number is 1 for most of case.